BAAQMD Title V Permit 6 Month Monitoring Report

From 1/1/2013 to 6/30/2013

	5/31/13 at 5:22 AM to 6/1/2013 at 5:33 AM.	Event Description: F-1100A NOx CEMS malfunction from 5/31/13 at 5:22 AM to 6/1/2013 at 5:33 AM.
	S4070	6/1/2013 5:33 AM
F-3550/60 NOx analyzer failed calibration on Saturday, 3/23/13 at 0501 hours. Last successful calibration occurred on Friday, 3/22/13 0510 hrs. Next good calibration occurred on Sunday, 3/24/13 at 0510 hours.	on Saturday, 3/23/13 at 0501 hours. Last successful calibration occ	Event Description: F-3550/60 NOx analyzer failed calibration
	S4038 P040	/24/2013 5:10 AM
	REVISED: F-1660 O2 analyzer was placed in service and calibrated on 3/18/13 at 1529 hours.	REVISED: F-1660 O2 analyzer was place
	F-1660 O2 analyzer failed Thursday, 3/14/13 at 1255 hours. Cause of failure unknown.	Event Description: F-1660 O2 analyzor failed Thursday, 3/14
	S4226	3/14/2013 12:55 PM 3/18/2013 3:29 PM Discovered On: 3/14/2013
successful calibration occurred on Saturday 3/9/13 at 0500 hrs (PST). Next good calibration occurred on Monday 3/11/13 at 0950 hrs.	Event Description: F-3550/3560 NOx and O2 CEMs failed calibration on Sunday, 3/10/2013 at 0600 hrs (PDST). Last successful calibration occurred on Saturday 3/9/13	Event Description: F-3550/3560 NOx and O2 CEMs failed co
	P040	3/9/2013 5:00 AM 3/11/2013 9:50 AM {
A CONTRACTOR OF THE PROPERTY O	F-731 NOx and O2 CEMs went inoperative starting on 3/8/13 at 0621 hrs. Repairs completed and good calibration occurred on 3/9/13 1009 hrs	Event Description: F-731 NOx and O2 CEMs went inoperation
	\$4169	3/8/2013 6:21 AM 3/9/2013 10:09 AM [
	letector.	
	√ \$4285	1/9/2013 12:20 AM 1/10/2013 5:22 AM E
P) CEM GLM Gas Parametri NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Wind Dir. Speed pH Temp. VOC. Press.	Abatement Emission Source (S#) Device (A#) Point (P#) Cl	Started Stopped
	Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below:	Inoperable monitors as defined by BAAQMD Regulation
Refinery Malling Address PO Box 12772 City: Richmond State: CA State: CA Zip Code: 94802-0272 Phone: (510) 242-2911	A0010 Chevron Richmond Refinery Facility Address: 841 Chevron Way: 841 Chevron Way: City: Richmond State: CA Zip:Code: 94801: Contact: Rachael Justice	

	Thursde
•	עלעל יינ
	25
	2013

Cogen 1000 Train NOx CEMs failed calibration on Tuesday, 6/25/2013 at 0500 hrs. Last successful calibration occurred on Monday 6/24/13 at 0725	Discovered On: 6/25/2013 Event Description: REFERENCING ID #06K98: PLEASE NOTE REVISION: INCLUDING TIME DURING THE END OF THE CALIBRATION ON 6/26.	6/24/2013 7:25 AM 6/26/2013 12:35 PM 😡 S4350	Event Description: FCC Flare water seal level indicator was inoperative from 6/18/13 at 0725 hours to 6/19/13 at 1007 hours.	6/18/2013 7:25 AM 6/19/2013 10:07 AM S4285 P0134 Discovered On: 6/19/2013	The wash water flow meter on the H2B Train Methanol Scrubber went inoperative on 6/8/13 at 0957 hours. Repairs ongoing.	Event Description: Please refer to BAAQMD # 06K75: Repairs completed on 6/11/13 at 0837 hours. Total inoperative time 6/8/13 at 0957 hours to 6/11/13 at 0837 hours.	6/8/2013 9:57 AM 6/11/2013 8:37 AM 🕢 S4250 Discovered On: 6/10/2013	Started Stopped Source (S#) Device (A#) Point (P#)	
oration occurred on Monday	OF THE CALIBRATION 01		s.		rs. Repairs ongoing.	837 hours.		Fuel CEM GLM Gas Parametri NOx SO2	
6/24/13 at 0725 hrs. Next good calibration occurred on Wednesday 6/26/13 at 1248 hrs.	N 6/26.							Opacity/ NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Wind Dir, Speed pH Temp. VOC. Press.	
.48 hrs.								Wind Dir. Speed pH Tem	
								Gauge p. VOC. Press.	

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

Signature

	•		
	Kory Judd	General Manager Richmond Refinery	
re of Responsible Official	Print Name	Title	Date